


WIRING DIAGRAM



F00237

**PARTS LIST FOR LESTER-MATIC CHARGER
MODEL 08882 TYPE 48LC25T12
115 VAC / 60 HZ**

PART NO.	DESCRIPTION
08883S	CASE ASSEMBLY
08614S	TRANSFORMER ASSEMBLY
16354S	HEATSINK ASSEMBLY, W/ DIODES
02000S	AMMETER
02002S	TIMER, 12 HOUR
02003S	KNOB, TIMER
02390S	CAPACITOR, 6.0 MFD, 660 VAC
02028S	BUSHING, 7W-2, INSULATOR FOR BOTH CORDS
02506S	CORDSET, AC
08512S	CORDSET, DC, NO PLUG
08020S	CORDSET, DC, W/ LESTER PLUG
08607S	CORDSET, DC, W/ 50 AMP ANDERSON PLUG
08224S	CORDSET, DC, W/ 175 AMP ANDERSON PLUG
14973S	CORDSET, DC, W/ SILICONE PLUG
08313S	PLUG ASSEMBLY, DC, 50 AMP ANDERSON PLUG
02957S	PLUG ASSEMBLY, DC, 175 AMP ANDERSON PLUG
08776S	FUSE ASSEMBLY
08778S	REPLACEMENT PART, FUSE AND HEATSINK ASSEMBLY